

ML19

| Work Order | Start Date | Status | Work description |
|------------|------------|--------|--|
| W15328 | 2-Jan-13 | F | General tidy up ready for paint/Sanding and tidy up work to be done by Mancala employees/and painting to be completed by William Adams Somerset |
| W15185 | 23-Jan-13 | F | Conduct repair assesment and cost study- Ex BCD Resources/Full pressure test and adjust of all compponents/Report to be completed, SMU of all components updated and/recorded. |
| W15412 | 25-Feb-13 | F | Diagnose & repair engine throttle fault, machine will not/adjust engine RPM via foot throttle, intermittant high idle/acceleration with out actuation of foot throttle. |
| W15420 | 25-Feb-13 | F | Replace machine batteries with new items due to the current/items not holding charge. |
| W16001 | 5-Jul-13 | F | Scope of works on rebuild of bucket./Tim Watts from William Adams to quote on rebuild. |
| W17900 | 14-Jan-14 | F | Refit turbo to aftercooler intake pipe/Refit brand new pipe assembly after old one was removed and/lent to Unity Henty until it was able to be replaced. |
| W18768 | 15-Apr-14 | F | Batteries U/S. To be replaced with 2 new ones./Both batteries flat. Charged and load tested which showed/they are both U/S. |
| W22966 | 22-Oct-15 | F | Fit serial number ID plate |
| W24823 | 4-Aug-16 | F | Fault in throttle circuit./Engine running at high idle upon start up |
| W30147 | 10-Jan-19 | F | Carry out 250Hrs service and repairs |
| W30193 | 15-Jan-19 | F | Carry out level 2 AFFF service and repairs |
| W30195 | 16-Jan-19 | F | Reseal lift and tilt cylinders |
| W30196 | 16-Jan-19 | F | Repair oil leak from sump gasket |
| W30197 | 16-Jan-19 | F | Clean, prepair and paint complete machine |
| W30198 | 16-Jan-19 | F | Source and install new pre cleaner assembly |
| W30199 | 16-Jan-19 | F | Repair or replace corroded injector pipes |
| W30201 | 16-Jan-19 | F | Fabricate new battery mount holder to fit new batteries |
| W30202 | 16-Jan-19 | F | Fabricate and install new transmission cover |
| W35303 | 21-Aug-20 | F | Need equipment number |
| W35304 | 21-Aug-20 | F | Missing guards |
| W35305 | 21-Aug-20 | F | No Reverse alarm |
| W35306 | 21-Aug-20 | F | No fire suppression |
| W34304 | 25-Aug-20 | F | Test and wash Machine, Machine Audit |
| W35302 | 16-Nov-20 | F | Crowd ram teaking |
| W38320 | 1-Apr-22 | F | Machine audit |
| W38322 | 5-Apr-22 | S | Repair and fabricate new panels |
| W38331 | 7-Apr-22 | F | Mechanical and Electrical repair to bring back to compliance |
| W38396 | 12-May-22 | F | Sandblast and paint ML 19 |
| W38437 | 25-May-22 | F | Re fit panels and stickers |
| W38431 | 26-May-22 | F | locatate remotes for ML 19 |
| W38438 | 2-Jun-22 | F | Dash repairs and wiring |
| W38477 | 21-Jun-22 | F | Repair Bucket, Paint Bucket and inside cabin |
| W38498 | 27-Jun-22 | F | Fit AFFF to Cat R1300 |
| W38529 | 7-Jul-22 | F | AFFF |
| W38543 | 12-Jul-22 | F | Replace damaged hydraulic hoses |
| W38744 | 28-Nov-22 | F | Replace cracked teeth on bucket/Fab trans guard |
| W38745 | 2-Dec-22 | L | Change tyres from slick to tread |
| W38753 | 6-Dec-22 | F | Change Tyres from slicks to tread |
| W38766 | 17-Dec-22 | F | Fit remotes |
| W38781 | 1-Jan-23 | F | Repair blown hydraulic hoses |
| W38834 | 16-Mar-23 | F | Wash loader and clean inside the cab |
| W38873 | 17-Apr-23 | F | Remove damaged wheel and hub assembly |
| W38937 | 30-May-23 | F | Service ML 19 |
| W39010 | 13-Jul-23 | F | REPLACE VALVE ON TYRE/CHANGE TYRE |